Dealer: US AUTO TRUST NEWPORT BEACH LLC

Engine Number: 17795030008146 Model: Vantage Coupe Auto

SCFSMGAW5MGN05846 Model Year:

Exterior Colour: China Grey

Black Alcantara/Obsidian Black Leather Interior Colour:

Owner Benefits: Port of Entry: Brunswick, GA Suggested Retail Price at P.O.E. 3 years unlimited mileage warranty

\$139,000.00

OPTIONAL EQUIPMENT

Trim Inlay - Satin Carbon Fibre Twill

20inch Lightweight Textured Black

24 hour roadside assistance

STANDARD FEATURES

Engineering and Performance Aston Martin Premium Audio Black Wings Badges 2-door coupe Bodypack - Black 503hp 4.0L Twin Turbo V8 Engine **Exterior Black Collection** 8-speed automatic transmission, rear-mid Optional Front End - Vaned Grille Electronic Rear Differential and Dynamic Black Hood Mesh Torque Vectorina Mirror Cap - Gloss Black 3 Selectable Drive Modes - Sport, Sport+, TrackSports Plus Seat (Sport Plus Collection) Full LED Headlights with integrated DRLs, side Roof Panel - Gloss Black lights, and cornering lights Rear Diffuser Inserts - Body Coloured One-Piece Aluminum Clamshell Hood Side Gill - Matte Black (perforated) Alloy torque tube with carbon fiber propeller Dark Chrome Jewellery Pack Smoked Rear Lamps 20" Alloy Wheels Umbrella

Safety and Security

Dynamic Stability Control (DSC), Traction Control (TC), and Positive Torque Control

Dual-Stage Driver & Passenger Front Airbags and Seat Mounted & Curtain Side Impact

Tire Pressure Monitoring System (TPMS)

Comfort and Convenience

12" Color TFT LCD Cluster

Rain-Sensing Wipers Electronic Park Brake (EPB)

garage door opener

8" Navigation System Bluetooth Phone & Streaming Audio Satellite Radio with Trial Subscription - 1yr Radio, 3yr Traffic Data iPhone® Integration and USB Input 360 Degree Camera with Front & Rear Parking Sensors Power Folding Heated Exterior Mirrors 8-Way Power Front Seats with 3-Position Power-Adjustable Tilt/Telescoping Steering

Dual-Zone Automatic Climate Control

Auto-dimming interior rear-view mirror with


Gas Guzzler

Transportation and handling

TOTAL SUGGESTED RETAIL*

\$0.00 \$3,086.00 \$172,786.00

*Total amount does not include state and local taxes or dealer installed accessories



\$5,300.00

Youspend Two Seater range from 11 to 36 MPG. **MPG** The best vehicle rates 141 MPGe. 24 over 5 years combined city/hwy highway city compared to the **\$0** average new vehicle. gallons per 100 miles gas guzzler tax Fuel Economy & Greenhouse Gas Rating (tailpipe only) Smog Rating (tailpipe only Annual fuel COST 4 10 10 This vehicle emits 435 grams CO2 per mile. The best emits 0 grams per mile (tailpipe only). Producing and

These estimates reflect new EPA methods

beginning with 2017 models.

Actual results will vary for many reasons, including driving conditions and how you drive and maintain your vehicle. The average new vehicle gets 27 MPG and costs \$7500 to fuel over 5 years. Cost estimates are based on 15,000 miles at \$3.25 per gallon. MPGe is miles per gallon equivalent. Vehicle emissions are a significant cause of climate change and smog.

tueleconomy.gov

Fuel Economy

Calculate personalized estimates and compare vehicles







Gasoline Vehicle

PARTS CONTENT INFORMATION

FOR VEHICLES IN THIS CARLINE: **U.S./CANADIAN PARTS CONTENT:**

MAJOR SOURCES OF FOREIGN PARTS CONTENT:

UK 66%

Germany 22%

NOTE: PARTS CONTENT DOES NOT INCLUDE FINAL ASSEMBLY, DISTRIBUTION OR OTHER NON-PARTS COSTS.

FOR THIS VEHICLE: FINAL ASSEMBLY POINT: Gaydon, Warwickshire, UK

COUNTRY OF ORIGIN: ENGINE PARTS:

GERMANY

TRANSMISSION PARTS: **GERMANY**

BUMPER QUALITY LABEL

THIS VEHICLE IS EQUIPPED WITH A FRONT BUMPER THAT HAS BEEN TESTED AT AN IMPACT SPEED OF 2.5 MILES PER HOUR, AND A REAR BUMPER THAT HAS BEEN TESTED AT AN IMPACT SPEED OF 2.5 MILES PER HOUR AND HAS SUSTAINED NO DAMAGE TO THE VEHICLE'S BODY AND MINIMAL DAMAGE TO THE BUMPER AND ATTACHMENT HARDWARE. MINIMAL DAMAGE TO BUMPER MEANS DAMAGE THAT CAN BE REPAIRED WITH THE USE OF COMMON REPAIR MATERIALS WITHOUT REPLACING PARTS. THE STRONGER THE BUMPER THE LESS LIKELY THE CAR WILL REQUIRE REPAIR AFTER A LOW SPEED COLLISION. (FOR CORNERS, THE IMPACT IS 60% OF THAT STATED AROVE) 60% OF THAT STATED ABOVE).

IMPORTANT NOTICE

THESE IMPACT SPEEDS ARE GOOD FAITH ESTIMATES OF THE SPEEDS AT WHICH THE DESCRIBED EXTENT OF BUMPER DAMAGE WILL NOT BE EXCEEDED BASED ON REASONABLE ENGINEERING JUDGMENT AND DATA FROM TESTING PURSUANT TO THE FEDERAL BUMPER STANDARD WHICH PROHIBITS DAMAGE TO THE VEHICLE BODY OR SAFETY SYSTEM IN 2.5 MPH IMPACTS, BUT SETS NO LIMIT ON DAMAGE TO BUMPERS AND THEIR ASSOCIATED COMPONENTS AND FASTENERS. THIS VEHICLE MEETS THE FEDERAL BUMPER STANDARD AT 2.5 MPH FRONT AND REAR, AND 1.5 MPH ON THE BUMPER CORNERS.

GOVERNMENT 5-STAR SAFETY RATINGS

This vehicle has not been rated by the government for overall vehicle score, frontal crash, side crash or rollover risk.

Source: National Highway Traffic Safety Administration (NHTSA) www.safercar.gov or 1-888-327-4236